



98210-1

USB 2.0 4 Port Flex Hub

Installation

1. Plug the hub into an available USB port on your computer.
2. Plug your devices into the open USB ports on the hub

Troubleshooting

Problem	Solution
The USB hub does not work.	Ensure your computer and operating system is USB compatible. Please check your equipment and operating manuals.
Connected USB devices operate erratically or not at all.	Some USB devices require more power than your computer can provide. Connect any external power sources to all applicable USB devices. If this does not solve the issue, unplug each connected device until the hub is working properly.

If you are having trouble with your hub or it is not working properly, please contact Jasco Products Company at www.jascoproducts.com or at 1-800-654-8483 Option 4 if prompted.

One Year Limited Warranty

Jasco Products Company warrants this product to be free from manufacturing defects for a period of one year from the original date of consumer purchase. This warranty is limited to the repair or replacement of this product only and does not extend to consequential or incidental damage to other products that may be used with this unit. This warranty is in lieu of all other warranties express or implied. Some states do not allow limitations on how long an implied warranty lasts or permit the exclusion or limitation of incidental or consequential damages, so the above limitations may not apply to you. This warranty gives you specific rights, and you may also have other rights which vary from state to state. If unit should prove defective within the warranty period, return prepaid with dated proof of purchase to:
Jasco Products Company
10 E Memorial Rd, Oklahoma City, OK 73114

FCC Statement

Notice: Federal Communications Commission (FCC) requirements, Part 15 This equipment has been tested and found to comply with the limits for a class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

CAUTION: Any changes of modifications not expressly approved by the grantee of this device could void the users authority to operate the equipment. This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

GE is a trademark of General Electric Company and is under license to
Jasco Products Company LLC,
10 E. Memorial Road, Oklahoma City, OK 73114
www.jascoproducts.com



Concentrador flex 4 puertos



98210-1

Instalación

1. Conecte el concentrador a un puerto USB disponible de su computador.
2. Conecte sus dispositivos a los puertos USB abiertos del concentrador

Resolución de problemas

Problemas	Solución
El concentrador USB no funciona.	Asegure que su computadora y su sistema operativo es compatible con USB. Verifique por favor su equipo y manuales de usuarios.
Los dispositivos de USB conectados no funcionan correctamente o en toda.	Algunos dispositivos de USB necesitan más poder que su computadora puede proporcionar. Conecte alguna fuente de alimentación externa a los dispositivos USB afectados. Si esto no resuelve el problema, desconecte cada dispositivo hasta que el hub trabaje correctamente.

Si el concentrador presenta problemas o éste no funciona de manera apropiada, póngase en contacto con Jasco Products Company en www.jascoproducts.com o en el número telefónico 1-800-654-8483, opción 4, si le piden una opción.

Garantía limitada de un año

Jasco Products Company garantiza que este producto está libre de defectos de fabricación durante un periodo de un año a partir de la fecha original de compra por el consumidor. Esta garantía se limita a la reparación o sustitución de este producto solamente y no se extiende a daños incidentales o derivados a otros productos que se usen con esta unidad. Esta garantía reemplaza a todas las demás garantías expresas o implícitas. Algunos estados no permiten las limitaciones en cuanto a la duración de garantías implícitas ni la exclusión o limitación de daños incidentales o derivados; por lo tanto, puede que las anteriores limitaciones no se apliquen en su caso. Esta garantía le otorga a usted derechos específicos y otros derechos que usted puede tener según el Estado en que reside. Si comprueba que la unidad es defectuosa dentro del periodo de garantía, devuélvala con porte prepago y prueba de compra con fecha a:
Jasco Products Company
10 E Memorial Rd, Oklahoma City, OK 73114

Declaración de FCC

Aviso: Requisitos de FCC (Comisión Federal de Comunicaciones), sección 15 Este equipo ha sido probado y cumple con los límites para un dispositivo digital clase B, de conformidad con la sección 15 de las normas de FCC. Dichos límites se diseñaron para ofrecer razonable protección contra interferencias perjudiciales en instalaciones residenciales. Este equipo genera, usa y puede irradiar energía de radiofrecuencia y, si no se instala y usa de acuerdo a las instrucciones, puede causar interferencias perjudiciales a las radiocomunicaciones. Sin embargo, no hay garantía de que no se presenten interferencias en una instalación en particular. Si este equipo causa interferencias perjudiciales a la recepción de radio o televisión (lo cual se puede determinar apagando y encendiendo el equipo), se anima al usuario a intentar corregir la interferencia mediante una de las siguientes medidas:

- Reoriente o reubique la antena receptora.
- Aumente la distancia de separación entre el equipo y el receptor.
- Conecte el equipo en un tomacorriente de un circuito diferente al que está conectado el receptor.
- Consulte con el distribuidor o con un técnico experto en radio y televisión para recibir ayuda.

PRECAUCIÓN: Los cambios o modificaciones no aprobados expresamente por el cesionario de este dispositivo podrían anular la autoridad del usuario para operar el equipo. Este dispositivo cumple con la sección 15 de las normas de FCC (Comisión Federal de Comunicaciones). Su funcionamiento está sujeto a las siguientes dos condiciones: (1) puede que este dispositivo cause interferencias perjudiciales, y (2) este dispositivo debe aceptar las interferencias recibidas, incluidas las que pueda causar un funcionamiento no deseado.

GE es una marca comercial de General Electric Company usada bajo licencia por Jasco Products Company LLC, 10 E. Memorial Road, Oklahoma City, OK 73114 www.jascoproducts.com